

FITNESS CERTIFICATE

To be filled by the inspecting officer (Asst.Engineer)

(Re:GO.Ms 20/70/PWD Dt.23-01-1970)

1. Name of the officer Mohandas O.G
2. Name of the school Santa maria public school and junior college kooroppada
3. Location with name of education District/sub District Kooroppada, Kottayam/pampady
4. Classification of building as specified in column 4 of the application for fitness certificate and size

	size with height in meters	Year
Pucca RCC Permanent Building three storied	1.a)25.40x8.30x11.50(12x6.15x6.75x3.6)	2002
	1.b)8.53x3x13(3x8.23x3.6)	2002
	2)18.60x7.80x13.25(9x6x6x3.60)	2008
	3)31.35x7.8x11.5 (12x6x6x3.60)	2008
	4)16.75x9.7x11.00	2008
Roof Top(Semi Permanent)	25.40x8.30x3.60(2x9.15x6.75x3.60 + 1 x 6.75x6.2x3.6)	

5. Period for which the certificate is issued 2019-20
6. Nature of defects if any, Nill
- a) Foundation and basement Nill
- b) Superstructure Nill
- c) Doors and windows Nill
- d) wood work wrought and put up Nill
- e) Roof Nill
- f) Flooring Nill
- g) Miscellaneous (cracks etc.) Nill
7. Any major defects noticed which will render the bulding unsafe in any manner Nill
8. Whether maintenance work have been done properly yes
9. Whether the structure is sound or not for conducting classes yes, Sound for conducting classes
- .Note:1.The stability of the structure should be examined also with reference to location, intensity of wind exposure of flood etc2.Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the school building was inspected by me Mohandas O.G on 7/09/2019 and found to be fit to conduct classes for the period 2019/2020 for the reasons stated above

Place Kooroppada

Date 07/09/2019

(seal)

Assistant Engineer



ASSISTANT ENGINEER
L.S.G.D. SECTION
KOOROPPADA G.P.